



Photo 1 – The Steen Skybolt, N22GL, at the end of the runway. Note how the main landing gear has spread apart and the airplane has settled.



Photo 2 - View at flooring inside cockpit. Note fractured landing gear shock cord truss.