



Photo 1 – View of the left side of the airplane (courtesy of the Federal Aviation Administration).



Photo 2 – View of the right side of the airplane (courtesy of the Federal Aviation Administration).



Photo 3 – View of the rear of the airplane (courtesy of the Federal Aviation Administration).



Photo 4 – View of a cup found at the accident site (courtesy of the Baxter County Sheriff's Office).



Photo 5 – View of a lid and straw found at the accident site (courtesy of the Baxter County Sheriff's Office).