



Photo 1 – FAA supplied photo of the accident airplane in a cornfield.



Photo 2 - FAA supplied close up photo of a deformation in the fuselage skin.



Photo 3 - FAA supplied overhead photo of the wreckage.



Photo 4 - FAA supplied photo of the cockpit controls.



Photo 5 - FAA supplied close up photo of the fuel filter.



Photo 6 - FAA supplied close up photo of the fuel quantity indicator.




Photo 7 - FAA supplied overhead photo of the engine.




Photo 8 - FAA supplied close up photo of a separation in an exhaust pipe.



Photo 9 - FAA supplied close up photo of a carburetor needle valve.



Photo 10 - FAA supplied close up photo of the engine monitor indicating a voltage of 12.9 volts.