



Photo 1 – Airplane in a field



Photo 2 – Front of airplane



Photo 3 – Damaged empennage



Photo 4 – Engine left side




Photo 5 – Magneto primary leads



Photo 6 – Magneto primary leads



Photo 7 – Magneto terminals



Photo 8 – Magneto drive shaft and contact assemblies



Photo 9 – Spark plugs