



Photo 1 – View of the left side of the wreckage in a cornfield (FAA Photo)



Photo 2 – View of wreckage in the cornfield (FAA Photo)



Photo 3 – View of wreckage in a hangar (FAA Photo)




Photo 4 – View of the top of the engine (CM Photo)



Photo 5 – View of carbon build-up on 1B sparkplug (CM Photo)



Photo 6 – View of carbon build-up on 3B sparkplug (CM Photo)



Photo 7 - View of carbon build-up on 5B sparkplug (CM Photo)



Photo 8 - View of carbon build-up on 2B sparkplug (CM Photo)



Photo 9 - View of carbon build-up on 4B sparkplug (CM Photo)



Photo 10 - View of carbon build-up on 6B sparkplug (CM Photo)