





Photograph 01 - Right Wing



Photograph 02 - Propeller Damage



Photograph 03 - Collapsed Left Main Landing Gear