



Photo 1 – Tire Marks Near Runway



Photo 2 – Tree Damage Near Runway



Photo 3 – Tree Damage



Photo 4 – Tree Damage



Photo 5 – Tire Marks Leading to Airplane



Photo 6 – Accident Airplane