



Photo 1 – Tree knocked down by helicopter



Photo 2 – Burnt Helicopter Wreckage



Photo 7 – Main Wreckage – Rotor mast



Photo 6 – Tree with impact damage




Photo 4 - Cell phone, displaying helicopter's last known position



Photo 5 - Engine inlet compressor



Photo 8 – Tree cut/slice



Photo 9 – Cut tree – likely from the main rotor blade



Photo 3 - Module 5, Slippage marks

Photo courtesy of Airbus