



Wreckage on hillside



Main rotor



Helicopter wreckage



Wreckage with ropes tied to it




View from wreckage



Wreckage after recovery



Damage noted during engine exam



Metal spray is noted on the turbine wheel during engine exam



Accident hillside

photo courtesy of Bell Helicopters



Helicopter wreckage on its side

photo courtesy of Bell Helicopters



Actuators during exam

photo courtesy of Bell Helicopters



Accident hill

photo courtesy of FAA



Helicopter wreckage

photo courtesy of FAA



Wreckage with ropes tied to it

photo courtesy of FAA



Wreckage Path

photo courtesy of FAA