



Photo 1: Oklahoma Highway Patrol Photo of the Airplane



**Photo 2: Ice on the Horizontal Stabilizer**



**Photo 3: Main Wreckage**



**Photo 4: Nose Landing Gear**



**Photo 5: De-Ice Tank**