



Photo 1 – Accident Site



Photo 2 – View of Left Side of Main Wreckage




Photo 3 – View of Fuselage



Photo 4 – View of Right Side of Main Wreckage



Photo 5 – Main Wreckage Cabin Area



Photo 6 – Left Engine and Propeller Assembly (FAA Photo)



Photo 7 – Right Propeller Assembly



Photo 8 – Propeller Assembly Fracture



Photo 9 – Witness Photo