



Photo 1 – Airplane wreckage at site (Front-right view)



Photo 2 – Airplane wreckage at accident side (Rear-right view)



Photo 3 – Wreckage during examination from front-right



Photo 4 – Wreckage during examination from front-left



Photo 5 - Engine