



Photo 1 – High aerial photo of accident site and debris



Photo 2 – Aerial photo of the accident from the front of the wreckage



Photo 3 – Close up aerial photo of the wreckage



Photo 4 – Main wreckage from the front



Photo 5 – Main wreckage from the front right




Photo 6 – Entire flight track



Photo 7 – End of flight track




Photo 8 – End of flight tracking facing west