


~~HC-17015~~
TRW

Propeller Owner's Manual & Log Book

D.O.A. — F.A.A.
APPROVED
MANUAL
NO. 139

For Propeller Models
HC-B3 ()
HC-B4 ()
HC-B5 ()
HC-A3 () (ALLISON)
Constant Speed,
Feathering,
and Reversing
Three, Four, and Five
Blade
May, 1984



Hartzell Propeller Products

TRW Aircraft
Components Group
P.O. Box 1458

Piqua, Ohio 45356

Telex

DESCRIPTION OF AIRCRAFT
AIRWORTHINESS DATA
BULLETINS,

DATE	TACH TIME	DESCRIPTION
4-20-10	7502 Hobbs.	inspected IAW an Airframe is airworthy condition. App

08/20/11	8252 Hobbs	
----------	------------	--

Removed and Reinstalled Off propeller from San Antonio Propeller. Work Order # 16313 - Aug 19, 2011. P/N HC-B3TN-3D, BUA30488, IAW Hartzell Propeller, Aircraft is approved for return to service. App [redacted]

11/21/2014	Hobbs 1410.5	AFTT: 8772.5
------------	--------------	--------------

I certify that this PROPELLER has been cleaned, serviced and inspected IAW FAR 43 Appendix D "100 Hr" criteria and/or manufactures instructions and deemed worthy for return of service.

04/01/2015	Hobbs 23750	
------------	-------------	--

I certify that this PROPELLER has been cleaned, serviced, and inspected IAW FAR 43 Appendix D "100 hr" criteria and/or manufactures instructions and deemed worthy for return of service.

03-19-2016		
------------	--	--

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND FOUND AIRWORTHY
A.B. [redacted] L.A. [redacted]

SAN ANTONIO PROPELLER SERVICE, INC.
SERVICEABLE PARTS TAG

Work Order 16313

Customer Order No. _____

Customer's Name ROWLAND DUSTING

Part Name PROPELLER Part Mfg. HARTZELL

Part No. HC-B3TN-3D Serial No. BUA30488

Remarks OVERHAULED I/A/W 118F, 133C AND 202A

MAINTENANCE RELEASE

This stamped paper is an official document and shall be kept with the AIRCRAFT'S OFFICIAL HISTORICAL RECORDS. Work accomplished under the above listed work order number is on file at this agency. The above component shall be inspected and inspected in accordance with the current FEDERAL AVIATION REGULATION, ground functionally tested and approved for return to service subject to Flight Operational Test. The mechanic making the installation must CW FAR 43.3

Signed _____

Date AUG 19 2011

San Antonio Propeller Service, Inc.

San Antonio, Texas 78216

FAA Approved Repair Station No: DM2R773K

SAN ANTONIO PROPELLER SERVICE, INC.
SERVICEABLE PARTS TAG

Work Order 16313

Customer Order No. _____

Customer's Name ROWLAND DUSTING

Part Name PROPELLER Part Mfg. HARTZELL

Part No. HC-B3TN-3D Serial No. BUA30488

Remarks OVERHAULED I/A/W 118F, 133C
AND 202A


MAINTENANCE RELEASE

This stamped paper is an official document and shall be kept with the AIRCRAFT'S OFFICIAL HISTORICAL RECORDS. Work accomplished under the above listed work order number is on file at this agency. The above component was repaired and/or inspected in accordance with the current FEDERAL AVIATION REGULATION, ground functionally tested and approved for return to service subject to Flight Operational Test. The mechanic making the installation must C/W FAR 43.9

Signed 

Date AUG 19, 2011

San Antonio Propeller Service, Inc.

 San Antonio, Texas 78216

FAA Approved Repair Station No. DM2R773K

DESCRIPTION OF AIRCRAFT
WORTHINESS DIRECTORIES
BULLETINS,

CH
ME DESCRIBED

502 Hobbs.

TAW an Annual
condition. App

52 Hobbs

Removed and Reinstalled Off propeller from San Antonio
eller. Work Order # 16313 - Aug 19, 2011. P/N HC-B3TN-3D,
BUA30488. TAW Hartzell 118F, 133C, 202A

DESCRIPTION OF ALL OPERATIONS PERTAINING TO
AIRWORTHINESS DIRECTIVES, SERVICE LETTERS,
BULLETINS, & MINOR ADJUSTMENTS

BLADE DWG NO. T10282+4
BLADE SER NO. 1. F73520

2. F76294

3. F76293

All of the Manufacturers instructions, letters and bulletins contained in the service manual referenced, plus those listed below have been accomplished during this repair:

SERVICE LTR. _____

HC-B3TN-3

AD Note 2009-10-14. c/w SB. 61-
313R3,61-097AR1,61-136R1,61-256. c/w.
SL. 61-614R3, 61-165,61-167,61-177,61-
188,61-217,61-299R1,154,159. c/w SI. 169.

SERVICE BUL. _____

A.D. NOTE _____

**DESCRIPTION OF ALL OPERATIONS PERTAINING TO
AIRWORTHINESS DIRECTIVES, SERVICE LETTERS,
BULLETINS, & MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
03/12/17	3163.5	I certify this prop. has been inspected TAW a 100hr. Inspection and is approved for return to service. A&P [REDACTED]	[REDACTED]
04-04-17	3189.4	TTAF: 10,551.4 TSP0H: 2608.9	
AD #'s 2005-18-20		Performed an Annual Inspection using Airtractor	
2005-14-12		M.M. & FAR 43 app. D as guide. Complied with	
2005-14-11		AD research & compliance of those applicable.	
96-18-14		I certify that this propeller has been through	
95-03-03		an Annual Inspection, Found to be Airworthy &	
94-03-11		this returned to service.	
83-0801R2		[REDACTED]	
74-14-01		Christopher DeLeon	
72-18-04		A&P# [REDACTED] IA	

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
03/30/18	3460.8	I certify this prop. has been inspected in accordance with a 100 hr. Inspection and is approved for return to service. A&P [REDACTED]	[REDACTED]

DATE: 04/1/2018
MODEL: HC-B3TN-3D
S/N: BUA-30488

REG No: N7314D
SMOH: 810.9
Hobbs: 3460.8

Performed an Annual Inspection in accordance with the Air Tractor AT502 Inspection Checklist and Hartzell Owner's Manual Periodic Inspection Checklist. Serviced propeller hub with Aeroshell 5 grease and lightly dressed propeller blades. A.D. compliance list was added to the permanent records. I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. End

Rolando Rodriguez A&P [REDACTED] A [REDACTED]