



Photo 1 – Wreckage Path



Photo 2 – Accident Airplane



Photo 3 – Engine, readied for test cell





Photo 4 - Fuel servos; accident servo (left), exemplar servo (right)



Photo 5 – Pitch trim



Photos – Piper Aircraft Company