



Photo 1 – View of the accident site, with the impact crater and the wreckage, looking to the north.



Photo 2 – View of the impact crater.



Photo 3 – View of the propeller.



Photo 4 – View of the engine.



Photo 5 – View of the cockpit.



Photo 6 – View of the empennage.



Photo 7 – View of the left section of the cockpit.



Photo 8 – View of the center section of the cockpit.



Photo 9 – View of the right section of the cockpit.



Photo 10 – View of the cockpit seat and the pilot’s flight helmet.



Photo 11 – View of the engine.