



Photo 1 – Main wreckage at accident site



Photo 2 – Right wing at accident site



Photo 3 – Left horizontal stabilator at accident site



Photo 4 – Right horizontal stabilator at accident site



Photo 5 – Left wing at accident site



Photo 6 – Fuel selector position as found at accident site



Photo 7 – Left view of engine prepared for test run



Photo 8 - Right view of engine prepared for test run



Photo 9 – Enlarged photo of fuel selector in accident airplane




Photo 10 – Exemplar photograph of new style fuel selector