



Photo 1 – Airplane wreckage in a corn field



Photo 2 – Left wing of burnt airplane



Photo 3 – Tail Section



Photo 4 – Left engine

Photo: Continental



Photo 5 – Engine sparkplugs, typical

Photo: Continental