



Photo 1 – Accident Scene, Photo from FAA



Photo 2 – Airplane Wreckage, Photo from FAA



Photo 3 – Reduction Gearbox and Propeller, Photo from FAA



Photo 4 – Propeller, Photo from FAA




Photo 5 – First Ground Scar, Photo from FAA



Photo 6 – Second Ground Scar, Photo from FAA