



Photo 1 – View of the left side of the engine.



Photo 2 - View of the right side of the engine.



Photo 3 - View of removed spark plugs.



Photo 4 - View of removed spark plugs.



Photo 5 - View of a removed magneto.



Photo 6 - View of a removed magneto.



Photo 7 - View of the removed carburetor.



12/04/2018

Photo 8 - View of the removed fuel filter from the carburetor.



Photo 9 - View of the carburetor fuel bowl containing a liquid and water testing paste with a positive indication.