



Photo 1 – Accident Site (Island Airways Photo)



Photo 2 – Accident Site (Island Airways Photo)



Photo 3 – Accident Site (Island Airways Photo)



Photo 4 – Accident Site (Island Airways Photo)



Photo 5 – Accident Site (Island Airways Photo)



Photo 6 – Accident Site (Island Airways Photo)



Photo 7 – Airframe Layout (Piper Photo)



Photo 8 – Center Fuselage / Cabin (NTSB Photo)



Photo 9 – Forward Fuselage / Cockpit (NTSB Photo)



Photo 10 – Instrument Panel / Throttle Quadrant (NTSB Photo)



Photo 11 – Left Wing (NTSB Photo)



Photo 12 – Right Wing (NTSB Photo)



Photo 13 – Vertical Stabilizer (NTSB Photo)



Photo 14 – Aft Fuselage / Horizontal Stabilizers (NTSB Photo)



Photo 15 – Left Engine (NTSB Photo)



Photo 16 – Left Propeller (NTSB Photo)



Photo 17 – Left Propeller (NTSB Photo)




Photo 18 – Right Engine (Lycoming Photo)




Photo 19 – Right Propeller (NTSB Photo)