



Photo 1 – Accident Site, Photo courtesy of the Ox Ranch Airport



Photo 2 – Accident Airplane, Photo courtesy of Lone Star Retrieval



Photo 3 – Airplane's Right Wing, Photo courtesy of Lone Star Retrieval



Photo 4 – Collapsed Right Main Landing Gear, Photo courtesy of Lone Star Retrieval



Photo 5 – Right Wing Flaps, Photo courtesy of Lone Star Retrieval



Photo 6 – Vertical Stabilizer, Photo courtesy of Lone Star Retrieval



Photo 7 – End of Runway 35, Photo courtesy of Lone Star Retrieval



Photo 8 – Tire Marks, Photo courtesy of Lone Star Retrieval



Photo 9 – Runway Scrapes, Photo courtesy of Lone Star Retrieval



Photo 10 – Runway Excursion Tire Marks, Photo courtesy of Lone Star Retrieval



Photo 11 – Tire Marks in the Grass Along the Runway, Photo courtesy of Lone Star Retrieval



Photo 12 – Heavy Tire Marks, Photo courtesy of Lone Star Retrieval



Photo 13 – Fence Damage, Photo courtesy of Lone Star Retrieval



Photo 14 – Accident Airplane and Ground Marks, Photo courtesy of Lone Star Retrieval