



Photo 1 – Accident site

photo courtesy of FAA



Photo 2 - Wreckage

photo courtesy of FAA



Photo 3 – Engine from accident airplane

photo courtesy of Lycoming



Photo 4 – Partly disassembled engine



Photo 5 - Broken camshaft

Photo courtesy of Lycoming




Photo 6 – Crack in crankshaft

photo courtesy of Textron



Photo 7 – Broken crankshaft

photo courtesy of Textron