



Photo 1 – View of the airplane after it came to rest (courtesy of the Menominee County Sheriff's Office).



Photo 2 – View of the airplane after it came to rest (courtesy of the Menominee County Sheriff's Office).



Photo 3 – View of the airplane after it came to rest (courtesy of the Menominee County Sheriff's Office).



Photo 4 – View of the airplane after it was recovered from the accident site (courtesy of the Menominee County Sheriff's Office).



Photo 5 – View of the airplane after it was recovered from the accident site (courtesy of the Menominee County Sheriff's Office).