



**Photo 1 – Damage to Left Wing Aileron and Upper Wing Skin (Courtesy of FAA)**



**Photo 2 – Damage to Lower Skin of Left Wing and Aileron (Courtesy of FAA)**