



Photo 1 – Right side view of the airplane in the dirt field (courtesy of the Federal Aviation Administration).



Photo 2 – Front view of the airplane in the dirt field (courtesy of the Federal Aviation Administration).



Photo 3 – View of the damage to the fuselage (courtesy of the Federal Aviation Administration).



Photo 4 – Front view of the airplane after recovery.



Photo 5 – Top view of the right engine.



Photo 6 – Right side view of the right engine.



Photo 7 – Top view of the left engine.




Photo 8 – Right side view of the left engine.



Photo 9 – View of the top right side engine spark plugs.



Photo 10 – View of the bottom right side engine spark plugs.



Photo 11 – View of the top left side engine spark plugs.



Photo 12 – View of the bottom left side engine spark plugs.