



Photo 1 – Airplane Submerged In Water (Photo Provided by Pilot)



Photo 2 – Airplane Being Towed to Shore by a Boat (Photo Provided by Pilot)



Photo 3 – Airplane Being Towed to Shore, Left Side (Photo Provided by Pilot)



Photo 4 – Airplane Being Towed to Shore, Rear (Photo Provided By Pilot)



Photo 5 - Battery Contactor Terminal for the Positive Battery Cable




Photo 6 - Battery Contactor Terminal for the Battery Switch and Starter Motor Contactor Cables