



Photo 1 – Airplane Wreckage

photo courtesy of FAA



Photo 2 – Drag Mark photo courtesy of FAA



Photo 3 – Propeller Cuts

photo courtesy of FAA



Photo 4 - Recovered Aircraft Wreckage

photo courtesy of Lycoming



Photo 5 – Engine

photo courtesy of Lycoming