



Photo 1 – Airplane on the grass runway



Photo 2 – Fractured tail section



Photo 3 – Fractured tail section



Photo 4 – A sectioned piece of the fractured tail section