



Photo 1 – View of chordwise abrasion on a propeller blade.



Photo 2 - View of the data plate.



Photo 3 - View of the engine primer.



Photo 4 - View of the carb heat selector. The selector is in the OFF position.



Photo 5 - View of the cockpit and instrument panel.



Photo 6 - View of the left side of the engine.



Photo 7 - View of the right side of the engine.



Photo 8 - View of a side of the carburetor.



Photo 9 - View of a side of the carburetor.



Photo 10 - Close-up view of the carburetor heat linkage.



Photo 11 - Close-up view of the No. 1 and 3 cylinders with their covers removed.



Photo 12 - Close-up view of the No. 2 and 4 cylinders with their covers removed.



Photo 13 - Close-up view of removed sparkplugs.



Photo 14 - Close-up view of removed sparkplugs.



Photo 15 - View of the oil screen cavity.



Photo 16 - View of the oil screen.



Photo 17 - View of the fuel screen.



Photo 18 - View of the removed fuel screen.



Photo 19 - View of the separated section of the carburetor venturi and butterfly throttle valve.



Photo 20 - View of the bent crankshaft and propeller flange.