



Photo 1 – View of the helicopter after it was recovered (courtesy of the Federal Aviation Administration).



Photo 2 – View of the main rotor head (courtesy of the Federal Aviation Administration).



Photo 3 – View of the main rotor mast (courtesy of the Federal Aviation Administration).



Photo 4 – View of the wire that was impacted (courtesy of the Federal Aviation Administration).