



Photo 1 – Airplane at Accident Site (Photo Courtesy of FAA)



Photo 2 – Engine Overview (Photo Courtesy of FAA)




Photo 3 – Engine Exhaust and Oil Cooler (Photo Courtesy of FAA)



Photo 4 – Eductor Interior Surface (Photo Courtesy of Honeywell)




Photo 5 – Fuel Control Unit and Fuel Pump Assembly (Photo Courtesy of Honeywell)