



Photo 1 – Number 3 cylinder, with failed exhaust valve

FAA photo



Photo 2 – Failed Exhaust valve

FAA photo



Photo 3 – Erosion on the number 4-cylinder exhaust valve

FAA photo