



Photo 1 – Airplane at Accident Site (Courtesy of Airport Operator)



Photo 2 – Alternator as Installed in Accident Airplane



Photo 3 – Accident Alternator with Damaged Front Housing (Left) and Accident Alternator with Exemplar Front Housing Installed for Testing (Right) (Courtesy of Manufacturer)