

Carburetor Icing Probability Graph – CEN19LA299

Airplane: N55633 - Piper, PA-28-140

Engine: Lycoming, O-320-E3D

Carburetor: Marvel-Schebler, Unknown Model

Fuel: 100LL

Accident Date: 08/31/2019

Accident Location: Conroe, TX

Accident Time: 0758 CDT

Weather: METAR KCXO 311253Z [0753 CDT] 00000KT
10SM BKN022 OVC035 23/22 A3005 RMK AO2 SLP171
T02330217

Celsius to Fahrenheit Conversion:

Temperature, 23° C = 73° F

Dew Point, 22° C = 72° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

