



Photo 1 – Accident Overview (Walkerton Police Department)



Photo 2 – Engine Mounted Fuel Filter (Rolls-Royce)



Photo 3 – Engine Mounted Fuel Filter Interior (Rolls-Royce)



Photo 4 – Fuel Spray Nozzle (Rolls-Royce)