



Photo 1 – View of the front of the powered parachute (courtesy of the Henderson County Sheriff's Office).



Photo 2 – View of the front seat and cockpit (courtesy of the Henderson County Sheriff's Office).



Photo 3 – View of the engine and the propeller (courtesy of the Henderson County Sheriff's Office).



Photo 4 – View of the parachute lines (courtesy of the Henderson County Sheriff's Office).



Photo 5 – View of the accident site and the downed wire (courtesy of the Henderson County Sheriff's Office).



Photo 6 – View of the wire next to the powered parachute (courtesy of the Henderson County Sheriff's Office).



Photo 7 – View of the utility pole’s height being measured from which the wire originated (courtesy of the Trinity Valley Electric Cooperative).