

Y	YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE
2	20			
0	DATE			

Description of Inspections, Tests, Repairs and Alterations
 Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

SKYPROS
 AVIATION

600 EE Kirby Rd. Grain Valley, Missouri 64029
 www.skypros.aero | [REDACTED]


N52LW

Date: January 12, 2017 Tach: 86.2 hrs
 Engine TSMOH: 86.2 Propeller TSN: 86.2

Removed all inspection panels, lubricate all bellcranks and control surfaces hinges, rod ends, check wing attachment bolts, checked all lights, placards and aircraft general condition.

Service all wheel bearings, greased and serviced landing gear. Retracted and extended landing gear. Replaced Battery. Serviced hydraulic power pack reservoir with hydraulic fluid. Fabricated and installed panel at cabin fuselage tail cone.

I certify that this aircraft has been inspected in accordance with the scope and details of appendix D part 43, and was found to be in a condition for a safe operation.



09/26/2019 11:32