



Photo 1 – Overall view of left wing damage to N520AK, a Piper PA-18 Super Cub.



Photo 2 – Left wing damage as seen from the top.



Photo 3 – Frontal view of left wing damage.



Photo 4 – Closer view of left wing damage.