



Photo 1 – Front view of the airplane (courtesy of the School of Missionary Aviation Technology).



Photo 2 – View of the damaged right aileron (courtesy of the School of Missionary Aviation Technology).



Photo 3 – View of the damaged right elevator (courtesy of the School of Missionary Aviation Technology).



Photo 4 – View of the left side of the tail wheel (courtesy of the School of Missionary Aviation Technology).



Photo 5 – View of the various tailwheel components (courtesy of the School of Missionary Aviation Technology).



Photo 6 – Rear view of the tailwheel (courtesy of the School of Missionary Aviation Technology).