



Photo 1 – Airplane on runway

Photo courtesy of the FAA



Photo 2 – Damage to the vertical stab and rudder

FAA photo



Photo 3 - Wing strut damage

FAA photo