



Photo 1 – Tire marks on runway from ground loop



Photo 2 – Broken tailwheel chain



Photo 3 – Front of airplane, damage noted on right wing