



Photo 1 – View of the runway and main wreckage facing north



Photo 2 – View of the runway and debris field facing northwest



Photo 3 – View of the road and debris field facing west



Photo 4 – View of the road and debris field facing east



Photo 5 – View of the initial impact area on the road and the debris field



Photo 6 – View from the end of the runway facing south



Photo 7 – Airplane and truck debris with the main wreckage in the background



Photo 8 – Engine and propeller where they came to rest in the debris field



Photo 9 – Engine and propeller and landing gear recovered to the road



Photo 10 – Airplane on top of the truck, rear



Photo 11 – Airplane on top of the truck, right rear



Photo 12 – Airplane on top of the truck, right



Photo 13 – Front left of truck with propeller slash marks and impact damage




Photo 14 – The pilot’s tablet showing the most recent flight and current location