



Photo 1 – Drone Footage of Wreckage

Photo: Hays County FD



Photo 2 – Drone Footage of Wreckage

Photo: Hays County FD



Photo 3 – Airplane Wreckage



Photo 4 – Engine buried in the ground, due to impact



Photo: Continental Aerospace



Photo: NTSB

Photo 5 - Engine Instruments