



Photo 1 – Left Side of Cockpit Instrument Panel Prior to Accident



Photo 2 – Center of Cockpit Instrument Panel Prior to Accident



Photo 3 – Right Side of Cockpit Instrument Panel Prior to Accident



Photo 4 – Overhead View of Accident Site



Photo 5 – Airplane at Accident Site



Photo 6 – Engine at Accident Site



Photo 7 – Propellers at Accident Site



Photo 8 – Directional Gyro