

# B200

Wreckage path

Legend

Skin Fragment near Fence

Blower

Avionics Boxes

Seat and Yoke

Left Elevator Tip

Instrument Panel

Seat 5

Left Inboard Flap

Left Side of Fuselage

Forward Cabin Door Frame

Left Wing Tip and Leading Edge Skin

Cabin Door

Horizontal Stabilizers and Elevators

Propeller Blade

Wing Skin Fragments and Collins Antenna

Right Landing Gear Trunnion

Aileron Fragment

Left Wing Tip Impact

Flap Fragments

Left Engine

Right Elevator Tip

Fuselage Impact

Wing Skin (Far Left)

Right Engine

Initial Impact - Right Wing Tip

