




Photo 1 – Aerial view of the accident site (courtesy of the Illinois Department of Transportation).



Photo 2 – View of the wreckage at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the wreckage at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the wreckage layout (courtesy of the Textron Aviation).



Photo 5 – View of the fuselage (courtesy of Textron Aviation).



Photo 6 – View of the empennage (courtesy of Textron Aviation).



Photo 7 – View of the propeller (courtesy of Lycoming Engines).



Photo 8 – Front view of the engine (courtesy of Lycoming Engines).



Photo 9 – Left side view of the engine (courtesy of Lycoming Engines).



Photo 10 – Right side view of the engine (courtesy of Lycoming Engines).



Photo 11 – Rear view of the engine (courtesy of Lycoming Engines).