



Photo 1 – Main Wreckage (Pilot Photo)




Photo 2 – Disconnected Choke Lever (Rotech Photo)



Photo 3 – Air Filters (Rotech Photo)




Photo 4 – Fuel Lines (Rotech Photo)



Photo 5 – No. 3 Exhaust (Rotech Photo)