



Photo 1 – Supplied view of the right side of the airplane resting on infield grass.



Photo 2 - Supplied view of the left side of the airplane resting on infield grass.



Photo 3 - Supplied view of the right outboard wing.



Photo 4 - Supplied close-up view of damage to the right outboard wing.



Photo 5 - Supplied close-up view of ice on the left outboard wing.



Photo 6 - Supplied view of ice on the ground under the leading edge of a wing.



Photo 7 - Supplied view of ice on the ground under the leading edge of a wing.



Photo 8 - Supplied close-up view of ice on the leading edge of the outboard left wing.