

-- CEN20LA063 --
Accident Site Diagram




Figure 1 – Accident Site Location (Provided by FAA)



OHIO TRAFFIC CRASH REPORT
DIAGRAM / NARRATIVE CONTINUATION

LOCAL REPORT NUMBER	REPORTING AGENCY Paulding County Sheriff's Office	DATE OF CRASH M 01 D 17 Y 2020
IN COUNTY OF Paulding	CRASH LOCATION ROAD 163, 0.4 MI N OF ROAD 138 IN FIELD	

RP to Base 5.2 FT

BASE

RP: Telephone company box #2-11022

ROAD 163 WIDTH = 20-10 FEET

ROAD 138

NOT TO SCALE

	AR	FE	DESCRIPTION
A	348 $\frac{1}{2}$	841 $\frac{1}{2}$	TAIL OF Plane
B	367 $\frac{1}{2}$	856 $\frac{1}{2}$	NOSE OF Plane
C	341 $\frac{1}{2}$	835 $\frac{1}{2}$	Left wing INSIDE
D	354 $\frac{1}{2}$	863 $\frac{1}{2}$	LEFT wing outside
E	355 $\frac{1}{2}$	862 $\frac{1}{2}$	Right wing INSIDE
F	360 $\frac{1}{2}$	863 $\frac{1}{2}$	RIGHT wing outside
G	355 $\frac{1}{2}$	851 $\frac{1}{2}$	WINDSHIELD
H	341 $\frac{1}{2}$	853 $\frac{1}{2}$	SIDE WINDOW

OFFICER'S SIGNATURE

BADGE NUMBER